# Oil Field Environmental Incident Summary

Responsible Party: ONEOK Rockies Midstream

Well Operator: Well Name:

Field Name: Well File #:

Date Incident: 3/11/2015 Time Incident: 13:00 Facility ID Number:

County: MCKENZIE Twp: 152 Rng: 101 Sec: 6 Qtr:

Location Description: Head north out of Alexander, ND on Hwy. 85 then head west on 41st Street

NW for 0.25 miles. The release site is 100 yards north of the gravel road in a

field.

Submitted By: Mitch Anderson Received By:

Contact Person: Mitch Anderson

2700 Lincoln Avenue SE Sidney, MT 59270

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident Pipeline Leak

Release Contained in Dike Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine

Other 0.5 Barrels 0.5 Barrels

**Description of Other Released Contaminant:** 

**Natural Gas Liquids (Condensates)** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There were no immediate health hazards associated with this release

Areal Extent:

40'L x 36'W

Tuesday, March 24, 2015 Page 1 of 2

## Potential Environmental Impacts:

There were no adverse environmental implacts associated with this release.

## **Action Taken or Planned:**

The line was blocked and valved out and will be capped to prevent future releases.

Wastes Disposal Location: All contaminated soil will be removed and transported to a licensed landfill.

Agencies Involved:

## **Updates**

Date: 3/11/2015 Status: Reviewed; Followup Required Staff: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

According to the incident summary, this spill impacted areas that are not associated with exploration and production. Followup is necessary.

Tuesday, March 24, 2015 Page 2 of 2